## DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Arnold Schwarzenegger, Governor

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-018852

Address: 333 Burma Road **Date Inspected:** 22-Dec-2010

City: Oakland, CA 94607

**Project Name:** SAS Superstructure OSM Arrival Time: 1500 **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** ShangHai, China

**CWI Name: CWI Present:** Yes Tian Lei No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

## **Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance(QA) Inspector, DJ Shin was present during the times noted above for observations relative to the work being performed.

### Bay 1

This QA inspector performed Magnetic Particle Testing (MT) and Visual Inspection (VT) of approximately 15 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as follows; Barrier Rail, on item number 1~5 of NWIT tracker document # 07892.

#### Bay 8

This QA Inspector observed the following work in progress for Bay 8.

ZPMC was using the Shield Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Liu Fa Wen.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector

Components: Bike Path PCMK: BK004A1-060-044

Welder: 67904

WPS-B-P-2211-TC-U4C

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





## **Summary of Conversations:**

No relevant conversations

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or 15000422372, who represents the Office of Structural Materials for remedial efforts please contact Eric Tsang your project.

Inspected By:	Shin,DJ	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer